To: Daly, Eric[Daly.Eric@epa.gov]

Cc: Ludmer, Margo[ludmer.margo@epa.gov]; Lisichenko, Peter[lisichenko.peter@epa.gov]; Scholand, Gregory

P.[gscholand@hselaw.com] **From:** Tuori, Thomas

Sent: Fri 8/4/2017 5:49:48 PM

Subject: RE: HTC Area 7 Gamma Survey

Hi Eric,

Thanks for checking in. We have used the same email address and I do not think we have received any "bounce back" emails. However -- we use a lower case "I": Iwi55@roadrunner.com.

Hope this works for you.

Tom



Thomas M. Tuori
Harter Secrest & Emery LLP, Attorneys and Counselors
1600 Bausch & Lomb Place, Rochester, NY 14604-2711
Firm 585.232.6500 Direct 585.231.1449 Fax 585.232.2152
ttuori@hselaw.com vCard Bio
www.hselaw.com

This e-mail message is from a law firm and may contain information that is privileged or confidential. It is not intended for transmission to, or receipt by, any unauthorized persons. If you have received this electronic mail transmission in error, do not read it. Please delete it from your system without copying it, and notify the sender by reply e-mail at ttuori@hselaw.com or by calling 585.231.1449, so that our address record can be corrected.

From: Daly, Eric [mailto:Daly.Eric@epa.gov]
Sent: Friday, August 04, 2017 1:38 PM

To: Tuori, Thomas

Cc: Ludmer, Margo; Lisichenko, Peter **Subject:** HTC Area 7 Gamma Survey

Hi Tom:

I just realized that I am receiving error messages for Walter's daughter email address: <u>Lwii55@roadrunner.com</u>. I am not sure if you have another contact email address or not. If so, please provide. I am going to the site in person soon and will bring a copy of the document to Walter. I will also ask him about the email address issue.

Thanks

From: Daly, Eric

Sent: Friday, August 04, 2017 1:32 PM

To: 'Lwii55@roadrunner.com' <<u>Lwii55@roadrunner.com</u>>; Tom Tuori (<u>ttuori@hselaw.com</u>) <<u>ttuori@hselaw.com</u>> Cc: Margo Ludmer (<u>ludmer.margo@epa.gov</u>) <<u>ludmer.margo@epa.gov</u>>; Peter Lisichenko (<u>lisichenko.peter@epa.gov</u>)

<lisichenko.peter@epa.gov>

Subject: HTC Area 7 Gamma Survey

Importance: High

Good Afternoon:

Attached is a brief summary for the gamma survey performed at 5382 Roberts Street in May 2017. EPA did not find any elevated levels on the outside property with the exception of the driveway area. (Not the driveway proper but some areas towards the property front lawn as well as the area between the driveways of 5380 and 5382 Roberts Street). EPA also detected elevated levels within the garage. Specifically, below the concrete slab. That is described in this summary. We assume the garage slab and the previous driveway were constructed at the same time and slag was placed below as foundation prior to concrete pour. Since the existing driveway was excavated and replaced, there are no elevated readings detected.

There were no elevated gamma levels detected within the interior of the home.

Radon canister results were provided to the group previously.

Please let me know if you have any questions. Thanks

Regards,
Eric M. Daly
On-Scene Coordinator/Radiological Response Specialist
US Environmental Protection Agency- Region II
ERRD/RPB/PPS
2890 Woodbridge Avenue
Edison, NJ 08837
daly.eric@epa.gov
908-420-1707

"We must, indeed, all hang together, or assuredly we shall all hang separately", Benjamin Franklin